

Message Text

UNCLASSIFIED

PAGE 01 STATE 098728
ORIGIN SY-05

INFO OCT-01 EA-12 ISO-00 /018 R

DRAFTED BY A/SY/OPS/T:R WALLER:SPL
APPROVED BY A/SY/OPS/T:W GILLIAM, ACTING CHIEF
A/SY/OPS/T:C PELCZYNSKI
DESIRED DISTRIBUTION
SY/OPS/FO/EA

-----056749 181437Z /42

R 181129Z APR 78
FM SECSTATE WASHDC
TO AMEMBASSY MANILA
INFO AMCONSUL HONG KONG
AMEMBASSY TAIPEI

UNCLAS STATE 098728

E.O. 11652: N/A

TAGS: ASEC

SUBJECT: BRUTE MECHANICAL FAILURES

MANILA FOR TSO, HONG KONG FOR RTC, TAIPEI FOR RSO, FROM A/
SY/OPS/T

REF: MANILA 4908

1. THE SARGENT AND GREENLEAF COMPANY HAS CORRECTED THE PROBLEM THAT YOU ENCOUNTERED WITH THE "BOLT PIN" BY INCREASING THE DIAMETER OF THE PIN, AND USING A DIFFERENT STAKING PROCEDURE OF THE PIN TO THE BOLT.
2. BEING FORWARDED TO YOU UNDER SEPARATE COVER ARE SIX IN-SWING AND SIX OUT-SWING BOLTS. ALSO INCLUDED WILL BE EXPLODED VIEW DRAWING OF THE LATEST MODEL 8497 "BRUTE" AND UNCLASSIFIED

UNCLASSIFIED

PAGE 02 STATE 098728

EARLIER MODEL 8480 "BRUTE". THE EXPLODED VIEW DRAWING HAS PART NUMBERS FOR FUTURE IDENTIFICATION OF PARTS THAT MAY FAIL, OR FOR ORDERING PURPOSES.

3. ALSO INCLUDED WILL BE A COMPLETE EXPLODED VIEW OF THE NUMBER 50 EXTENSION WITH PART NUMBERS.

4. PLEASE ADVISE A/SY/OPS/T IF THE LOCK BOLT PIN ON THE

NEW BOLT DOES NOT HOLD UP. IF FAILURES CONTINUE WITH THE
NEW BOLT, WE WILL HAVE FURTHER DISCUSSIONS WITH S AND G. CHRISTOPHER

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 18 apr 1978
Decaption Date: 01 jan 1960
Decaption Note:
Disposition Action: n/a
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 jan 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978STATE098728
Document Source: CORE
Document Unique ID: 00
Drafter: R WALLER:SPL
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Expiration:
Film Number: D780165-1030
Format: TEL
From: STATE
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t19780444/aaaabkyd.tel
Line Count: 66
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: f58007ac-c288-dd11-92da-001cc4696bcc
Office: ORIGIN SY
Original Classification: UNCLASSIFIED
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: n/a
Previous Handling Restrictions: n/a
Reference: 78 MANILA 4908
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 01 jun 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 2929985
Secure: OPEN
Status: NATIVE
Subject: BRUTE MECHANICAL FAILURES MANILA FOR TSO, HONG KONG FOR RTC, TAIPEI FOR RSO, FROM A/ SY/OPS/T
TAGS: ASEC
To: MANILA
Type: TE
vdkgvwkey: odb://SAS/SAS.dbo.SAS_Docs/f58007ac-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014